

In-Wall Dehumidifier Surface Mount Kit



Part No. 4037766

Parts Included:

1. Surface Mount
2. Screw A (x5) - Pan Head, coarse pointed screw for wood
3. Screw B (x5) - Truss Head, self-drilling screw for metal studs
4. Plastic Grommet / Drain Hose Bushing

Tools Required:


- Drill/Screwdriver
- Long Bit Extender (optional)



Step 1. Attach Surface Mount to Wall

Locate studs inside the wall 16" apart. Place the surface mount on the wall and ensure it is level.

Locate the four holes on the surface mount and fasten to the wall with the appropriate screws based on the stud type. Screw A can be used for wood studs and Screw B can be used for metal studs.



CONTINUED



Therma-Stor®

4201 Lien Rd Madison, WI 53704 • TOLL-FREE 1-800-533-7533 • www.thermastor.com • sales@thermastor.com



TS-1050 1/18 Rev A

Step 2. Prepare Surface Mount for In-Wall Dehumidifier Installation

Punch the appropriate knock out holes for the drain hose and electrical wiring.

If using conduit, pass pipe through the knock out hole before installing the dehumidifier.

Install included plastic grommet for drain hose.




Step 3. Install In-Wall Dehumidifier to Surface Mount

Lift and support the dehumidifier by the plastic drain pan below the evaporator coil and place inside of the surface mount. Two people are recommended for this step.

Route the drain hose and electrical wiring through the corresponding knock out holes of the surface mount and dehumidifier to connect.

Locate the four slotted holes on the dehumidifier. Use Screw A to fasten the unit to the surface mount through the slotted holes.



CONTINUED
→




Therma-Stor®

4201 Lien Rd Madison, WI 53704 • TOLL-FREE 1-800-533-7533 • www.thermastor.com • sales@thermastor.com
TS-1050 1/18 Rev A


Step 4. Install Diffuser Cover

Place the hooks of the front diffuser cover into the slots at the base of the dehumidifier before fastening.



SECURE BOTH
HOOKING LOCATIONS

Locate the four holes on the diffuser cover and fasten to the dehumidifier using either Screw C (Tamper Resistant) or Screw D (Phillips Head) included with the unit. Using the tamper resistant screws requires the 1/4" Hex T-15 Torx Security Bit included with the unit as well



SCREW C OR D



Therma-Stor®

4201 Lien Rd Madison, WI 53704 • TOLL-FREE 1-800-533-7533 • www.thermastor.com • sales@thermastor.com

TS-1050 1/18 Rev A